Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW4059/1

Work Order Type: Weatherization

Audit Name: Audit-12012NW4059

CLIENT INFORMATION

Client Name: 12012NW4059 Address:

38242 Client ID: 12012NW4059

Alt. Client ID: Henry

CLIENT CONTACT INFORMATION

12012NW4059 Applicant/Person of **V**

Record

AGENCY INFORMATION

Agency: Northwest TN EDC Agency Phone: (731) 364-3228

Address: 231 S. Wilson Street Fax:

> Dresden, TN 38225 **Email Address:**

Agency Contact: Radford, Randy Work Phone: (615) 686-3245

Cell Phone: (615) 335-7428

Email Address: Randy@energyhoundz.com

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

Contractor to follow the Southeast Field Guide as applicable.

Client Name: 12012NW4059 Client ID: 12012NW4059 Alt. Client ID: Henry

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: WO/12012NW4059/1 Version 8.6.0 Report Run On: 5/24/2010 Page 1 of 4

Measures

| | eplace Dog Access Door i ouse (approx. 12 x 18) | n Back of | F | Component | ts | | 1 | nspected |
|--|--|----------------------|----------------|---------------------------------|-------|--------|---------------------|-----------|
| Comment | | | | | | | | |
| | | | Estimated | | | Actual | | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Labor | | | 1 | | | | | |
| 2 Doors | | | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | , | Sub Total: | |
| | | | | | | | | |
| | eatherstrip Around All Do | ors | | Component | ts | | 1 | nspected |
| Measure 2 W Comment | eatherstrip Around All Do | ors | | • | | | | Inspected |
| | eatherstrip Around All Do Description / Comment | ors <i>Unit</i> s | Qty | Component Estimated Unit Cost | | Qty | Actual Unit Cost | Inspected |
| Comment | | | | Estimated | | Qty | Actual | |
| Comment # Material / Labor | | | Qty | Estimated | | Qty | Actual | |
| Comment# Material / Labor1 Labor2 Doors | | | Qty 1 | Estimated | | Qty | Actual | |
| Comment# Material / Labor1 Labor | | | Qty 1 | Estimated | | Qty | Actual | |
| Comment# Material / Labor1 Labor2 Doors | | | Qty 1 | Estimated | | Qty | Actual | |
| Comment# Material / Labor1 Labor2 Doors | | Units | Qty 1 1 | Estimated | | | Actual | |

| Comment | r Ins. R-19 | | | Component | ts Crawl | 1 | Ins | |
|---|---|----------------------|----------------|--------------|----------|------|------------|----------|
| | | Estimated | | | Actual | | | |
| # <i>Material / Labor</i> Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Insulation | Floor Insulation - Fiberglass Batts - R-19 | SqFt | 946 | | | | | |
| Other Detail | | | | | |] [| | |
| | | | | | |] [] | | |
| | | | Measur | e Sub Total: | |] . | Sub Total: | |
| | | | | | | | | |
| | Monitor is Needed | | | Component | | | | Inspecte |
| Comment | | | | Estimated | | | Actual | |
| Comment # Material / Labor | Description / Comment | <i>Units</i> Each | Qty 1 | • | | Qty | | Inspecte |
| Comment # Material / Labor 1 Health and Safety | Description / Comment | | Qty | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety | Description / Comment CO monitor | Each | Qty 1 | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety 2 Labor | Description / Comment CO monitor | Each | Qty 1 | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety 2 Labor | Description / Comment CO monitor | Each Hour | Qty 1 1 | Estimated | | | Actual | |

| cription / Comment hroom exhaust fan or Detector is Needed | Units Each Hour | | Estimated Unit Cost | Total | Qty | Actual Unit Cost | Total |
|---|-----------------|----------------------------|---------------------------------|---|---------------------|--|--|
| hroom exhaust fan | Each Hour | 1 1 Measur | Unit Cost | | | Unit Cost | Total |
| hroom exhaust fan | Each Hour | 1 1 Measur | | Total | | | Total |
| por | Hour | 1 Measur | e Sub Total: | | | Sub Total: | |
| | | Measur | e Sub Total: | | | Sub Total: | |
| etector is Needed | | | e Sub Total: | | | Sub Total: | |
| etector is Needed | | | e Sub Total: | | | Sub Total: | |
| etector is Needed | | | e Sub Total: | | | Sub Total: | |
| etector is Needed | | | e Sub Total: | | | Sub Total: | |
| etector is Needed | | | | | | | |
| | | | Componen Estimated | | | | nspected |
| cription / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| | Each | 1 | | | | | |
| oor | Hour | 1 | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | Measur | e Sub Total: | |] , | Sub Total: | |
| | | | | | | | |
| • | oke detector | oke detector Each oor Hour | oke detector Each 1 oor Hour 1 | oke detector Units Qty Unit Cost Each 1 | oke detector Each 1 | oke detector Hour Hour | oke detector Hour Hour |

Client Name: 12012NW4059 Client ID: 12012NW4059 Alt. Client ID: Henry DOE Weatherization Assistant Version 8.6.0 Page 4 of 4

Report Run On: 5/24/2010